


Note: Tangential porting is uni-directional. Gland is illustrated for CCW shaft rotation from drive end.



Plan 52 Dual Seals, Unpressurized